



INTERNATIONAL CERTIFICATION SERVICES, INC.

REGULATORY COMPLIANCE AND PRODUCT CERTIFICATION SERVICES

Client: Neoptx
2205 152nd Ave. NE
Redmond, WA 98052
USA

ANSI Z87.1-1989; Frame Test Par. 8.2.1.1; High Mass Impact

Result: Pass

Sample ID	Location	Pass/Fail
3-1	Right Ocular	Pass
3-2	Left Ocular	Pass
3-3	Right Ocular	Pass
3-4	Left Ocular	Pass

ANSI Z87.1-1989; Frame Test Par. 8.2.1.2; High Velocity Impact

Result: Pass

Sample ID	Location	Velocity (ft/sec)	Pass/Fail
3-15	Right Ocular 15° Nasal	148	Pass
3-16	Right Ocular 0°	151	Pass
3-17	Right Ocular 15° Temporal	152	Pass
3-18	Right Ocular 30° Temporal	152	Pass
3-19	Right Ocular 45° Temporal	150	Pass
3-20	Right Ocular 60° Temporal	152	Pass
3-21	Right Ocular 75° Temporal	152	Pass
3-22	Right Ocular 90° Temporal	152	Pass
3-23	Right Ocular 90° Temporal +10mm	152	Pass
3-24	Right Ocular 90° Temporal -10mm	151	Pass
3-5	Left Ocular 15° Nasal	151	Pass
3-6	Left Ocular 0°	151	Pass
3-7	Left Ocular 15° Temporal	149	Pass
3-8	Left Ocular 30° Temporal	152	Pass
3-9	Left Ocular 45° Temporal	152	Pass
3-10	Left Ocular 60° Temporal	151	Pass
3-11	Left Ocular 75° Temporal	151	Pass
3-12	Left Ocular 90° Temporal	152	Pass
3-13	Left Ocular 90° Temporal +10mm	150	Pass
3-14	Left Ocular 90° Temporal -10mm	152	Pass